


## Completion Report

|    |                                        |                                                                                                      |        |              |
|----|----------------------------------------|------------------------------------------------------------------------------------------------------|--------|--------------|
| 1  | Name of Work                           | Desilting and Re-Setting of drains and Re-Asphalting to Siddeshwara Layout in Bagalagunte ward No 14 |        |              |
| 2  | Sanctioned Estimate No.& Date          | SE/DZ/TS/02/21-22, Dt.20.05.2021                                                                     |        |              |
| 3  | Head of Account which is Chargeable    | P-                                                                                                   |        |              |
| 4  | Enstrument Order No. & Date            | EE/DD/WO/ 27/22-23, Dt.27.06.2022                                                                    |        |              |
| 5  | Name of Contractor                     | Govindaraju                                                                                          |        |              |
| 6a | Time Stipulated for Completion of work |                                                                                                      |        |              |
| b  | Delay in execution of work             | -                                                                                                    |        |              |
| 7  | Measurement recorded in MB             | 662/17-18                                                                                            |        |              |
|    | Page No                                | 66140 to 66142                                                                                       |        |              |
| 8  | check Measurement of the Asst          | -                                                                                                    |        |              |
|    | Exe. Eng./ Exe.Eng. On                 | -                                                                                                    |        |              |
| 9  | Name of the Office / Official          | Asst.Executive Engineer<br>T.Dasarahalli Sub Division                                                |        |              |
|    | incharge of the work                   |                                                                                                      |        |              |
| 10 | a)Assistant Engineer                   | Venkateshappa                                                                                        |        |              |
|    | b) Asst. Exe. Engineer                 | B R Ranganath                                                                                        |        |              |
|    | Sanctioned Estimate amount             | Amount claims as per actually vide as per bills                                                      | Excess | Savings (Rs) |
|    | Rs 50.00 lakhs                         | Rs 4613924.00                                                                                        | -      | -            |

- 1) Certified that the above work has been Completed within the stipulated time nited in the
- 2) Certified that the Contractor has delayed and completed the work for which necessary fine recovered
- 3) Certified that the above work has been executed by the contractor satisfactory in

  
ASSISTANT ENGINEER

  
**EXECUTIVE ENGINEER**  
Bruhat Bangalore Mahanagara Palike  
Dasarahalli Division, Bangalore - 560 057.

  
ASSISTANT EXECUTIVE ENGINEER  
T.DASARAHALLI SUB-DIVISION